

architecture | structure | interior

TO WHOMSOEVER IT MAY CONCERN

This is to certify that the structural condition of the building of Saint Joseph Senior Secondary School, Khasra Number- 154, 156/1, 156/2, 156/3, Patwari Halka Number- 114, Amlidih, Raipur is visually good and sound. Upon my visit to the school premises following the request from the school authority on 25/01/2020, I inspected the building. There is no need of any kind of repairing as the building is safe and sound for running the school.

Hem Kurrar Jain

Mpl. Corno. 18 1 100

Savron Bazes & partic G

